

# TAMAR SECURITY

DOMESTIC AND COMMERCIAL FIRE AND SECURITY SOLUTIONS

Ulysses Park, Exeter, Devon EX2 7PH

T: 01392 368830

E: admin@tamarsecurity.co.uk

www.tamarsecurity.co.uk

## CUSTOMER JOB NO. 250222 - 102052 - Justin Chaplin Fire Alarm - Maintenance

Site Details	
<b>Name</b>	Stowford Community Centre
<b>Address</b>	Chambers Close Sidmouth Devon EX10 9YL
<b>Contact</b>	Bob Weeks
<b>Telephone</b>	01395 576803
<b>Mobile</b>	07973252834
<b>Email</b>	

Customer Details	
<b>Name</b>	Stowford Community Centre
<b>Address</b>	Chambers Close Sidmouth Devon EX10 9YL
<b>Contact</b>	
<b>Telephone</b>	01297 33554
<b>Mobile</b>	
<b>Email</b>	stowfordcommunity@btconnect.com

Work Requested
Fire Alarm Annual

Schedule						
Date Schedule	Date Performed	Scheduled Start	Scheduled Finish	Actual Start	Actual Finish	Total
03/02/2026	03/02/2026	11:45	12:45	11:30	12:45	1.25 hrs

Work to be Performed	
Description	Required

Work Completed
Routine service of fire alarm system. Tested 50% Tested loft spaces Tested children centre rooms.. Tested mcps. Tested kitchen and main hall Batteries tested ok. Recommendations. 1) main fused spur not fire rated to bs 5839 2025 2) zone chart is a bit confusing Log book completed

Asset Register - 2: System: Fire Alarm - Commercial - BS5839:2025							
Asset ID	System Description	Location	Make	Model	Grade/Level	Date Tested	Pass / Fail
6141	Fire Alarm:	##Fire panel is				03/02/2026	Pass

Tamar Security Ltd is registered in England and Wales, Registration No. 05455843  
VAT Registration No. 857 7423 87  
Director: Martin Shearer



CERTIFICATE NO. NAC/G/1835

# TAMAR SECURITY

DOMESTIC AND COMMERCIAL FIRE AND SECURITY SOLUTIONS

Ulysses Park, Exeter, Devon EX2 7PH

T: 01392 368830

E: admin@tamarsecurity.co.uk

www.tamarsecurity.co.uk

## CUSTOMER JOB NO. 250222 - 102052 - Justin Chaplin Fire Alarm - Maintenance

Asset ID	System Description	Location	Make	Model	Grade/Level	Date Tested	Pass / Fail
	BS5839-Part 1 (Commercial)	a Twin Surveyor XLKHS in entrance lobby.## Apollo series 65 protocol. Customer test EL's themselves*** Fire - Annual service requires poles for high level smokes .					
<b>Test Readings</b>	Is the system log book available: Yes				Any false alarms noted in Log Book. Does the number exceed 1 per 25 detectors: 0		
	What category does system look like, if no spec on site: L2				Remote signalling, if applicable check and confirm with ARC time signal received Fire@ Fault@: Not applicable		
	Check all Fire Alarm functions of the FAP: Yes				Check all LED illumination indicators and displays on FAP: Yes		
	Check all fault indicators by simulating faults: Yes				Is zone diagram in place and correct: Yes		
	Confirm visually all cables are securely clipped with fire resisting clips as appropriate: Yes				Battery current in quiescent in MA: 100		
	Battery current in alarm in MA: 1010				Calculate battery size $c=[(i1 \times T1)+i2] \times 1.25$ : 4.105		
	Confirm all MCPs not obstructed: Yes				Operate and MCP or automatic detector on each conventional FAP zone: Zones 2 and 3 tested		
	Functionally test Automatic Detectors i.e 25%,50%,75% or 100% against schedule or colour code and note any not tested: 50%				Carry out sounder test and confirm all sounders working: Sounders tested		
	Confirm clear space of 500mm is maintained below each automatic detector: Yes				Confirm storage does not encroach within 300mm of a ceiling: Yes		
	Test all cause and effects: Yes				Confirm site is left tidy and all surplus materials removed: Yes		
Confirm system is free of all faults and fully operational: Yes				Complete Log Book and inform responsible person of result of visit: Log book completed			
<b>Notes</b>	See report for recommendations						

### Asset Register - Fire Alarm System Component

Asset ID	Location/Type	Floor	Type	Zone	Make	Date Tested	Pass / Fail
15317	front entrance by panel		MCP	3		03/02/2026	Pass
<b>Test Readings</b>	Visual Inspection:			Functional Test:			
<b>Notes</b>							
15321	birch		Smoke Detector	3		03/02/2026	Pass
<b>Test Readings</b>	Visual Inspection:			Functional Test:			

Tamar Security Ltd is registered in England and Wales, Registration No. 05455843  
VAT Registration No. 857 7423 87  
Director: Martin Shearer



CERTIFICATE NO. NAC/G/1835

# TAMAR SECURITY

DOMESTIC AND COMMERCIAL FIRE AND SECURITY SOLUTIONS

Ulysses Park, Exeter, Devon EX2 7PH

T: 01392 368830

E: admin@tamarsecurity.co.uk

www.tamarsecurity.co.uk

## CUSTOMER JOB NO. 250222 - 102052 - Justin Chaplin Fire Alarm - Maintenance

Notes							
15322	kitchen		Heat Rate of Rise Detector	3		03/02/2026	Pass
Test Readings	Visual Inspection:			Functional Test:			
Notes							
15323	kitchen fire exit		MCP	3		03/02/2026	Pass
Test Readings	Visual Inspection:			Functional Test:			
Notes							
15324	pine hall		Smoke Detector	2		03/02/2026	Pass
Test Readings	Visual Inspection:			Functional Test:			
Notes							
15325	pine hall		MCP	2		03/02/2026	Pass
Test Readings	Visual Inspection:			Functional Test:			
Notes							
15328	Oak hall		Smoke Detector	2		03/02/2026	Pass
Test Readings	Visual Inspection:			Functional Test:			
Notes							
15329	Oak hall fire exit double doors		MCP	2		03/02/2026	Pass
Test Readings	Visual Inspection:			Functional Test:			
Notes							
15330	Oak hall fire exit single door		MCP	2		03/02/2026	Pass
Test Readings	Visual Inspection:			Functional Test:			
Notes							
15332	children centre office		Smoke Detector	3		03/02/2026	Pass
Test Readings	Visual Inspection:			Functional Test:			
Notes							
15333	children centre office electric cupboard		Smoke Detector	3		03/02/2026	Pass
Test Readings	Visual Inspection:			Functional Test:			

Tamar Security Ltd is registered in England and Wales, Registration No. 05455843  
VAT Registration No. 857 7423 87  
Director: Martin Shearer



CERTIFICATE NO. NAC/G/1835

# TAMAR SECURITY

DOMESTIC AND COMMERCIAL FIRE AND SECURITY SOLUTIONS

Ulysses Park, Exeter, Devon EX2 7PH

T: 01392 368830

E: admin@tamarsecurity.co.uk

www.tamarsecurity.co.uk

## CUSTOMER JOB NO. 250222 - 102052 - Justin Chaplin Fire Alarm - Maintenance

<b>Notes</b>							
15336	class room by office		Smoke Detector	3		03/02/2026	Pass
<b>Test Readings</b>	Visual Inspection:			Functional Test:			
<b>Notes</b>							
15337	meeting room next to kitchen		Smoke Detector	3		03/02/2026	Pass
<b>Test Readings</b>	Visual Inspection:			Functional Test:			
<b>Notes</b>							
15338	main office rhs of kitchen		Smoke Detector	3		03/02/2026	Pass
<b>Test Readings</b>	Visual Inspection:			Functional Test:			
<b>Notes</b>							
15339	children centre office		Smoke Detector	3		03/02/2026	Pass
<b>Test Readings</b>	Visual Inspection:			Functional Test:			
<b>Notes</b>							
15341	small meeting room		Smoke Detector	3		03/02/2026	Pass
<b>Test Readings</b>	Visual Inspection:			Functional Test:			
<b>Notes</b>							
15342	hallway fire exit		MCP	3		03/02/2026	Pass
<b>Test Readings</b>	Visual Inspection:			Functional Test:			
<b>Notes</b>							
15345	Big Loft		Smoke Detector	4		03/02/2026	Pass
<b>Test Readings</b>	Visual Inspection:			Functional Test:			
<b>Notes</b>							
15346	Big Loft		Smoke Detector	4		03/02/2026	Pass
<b>Test Readings</b>	Visual Inspection:			Functional Test:			
<b>Notes</b>							
15347	Big Loft		Smoke Detector	4		03/02/2026	Pass
<b>Test Readings</b>	Visual Inspection:			Functional Test:			
<b>Notes</b>							

Tamar Security Ltd is registered in England and Wales, Registration No. 05455843  
VAT Registration No. 857 7423 87  
Director: Martin Shearer



CERTIFICATE NO. NAC/G/1835

